Work Orde	er ID 85668 6:57 PM			*856	368*							Page 1	
Revision ID:	D412-664-203 Crosstube Aft			Accept	*N900	040	100)* s	etup	Start Stop	*N:	S1* S2*	
Start Date: Required Date: Reference:	6/14/12 Req'd Q	ty: 1.00 pty: 1.00 - RETURA	*1* *1*	· ·	Cust Item I Customer:		OAR001						
Approvals:	Process Plan: Date:			Tooling:	Da	Date:			Run	Start	*NR1*		
	QC:	Date	:	SPC (Y/N):	Da	Date:				Stop	*NR2*		
Sequence ID/ Work Center II	Operation Descript			Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp	
Draw Nbr	Revision Nbr												
D412-664-243	E/DEO							746					
100				0.00									
100 QC Quality Control		Memo INSPECT RA111377 1 X D412-664-203 B	83182 CHG	0.00 Salan	113							·	
110				0.00				A					
110 Crosstubes		Memo SCRAP/DESTROY 1	гиве	0.00				13	(J_		06 · C	'	
120 *120*	QC21- Fin	al Inspection - Work O	rder Release	0.00						12)	(2) W	44	
QC		Memo		0.00						19	W 1,0		
Quality Control										Mc	51	100/1	

Page 1

Work Order ID:

85668

Parent Item:

D412-664-203

Parent Item Name:

Crosstube Aft

Start Date: 6/13/12

Required Date: 6/14/12

Start Qty: 1.00

Required Qty: 1.00

Comments:

IPP Rev:E04.02.16Reformat; Added D3189-1K/DS

 IPP Rev:F
 06-03-29
 Remove Coments on Pick List
 JLM

 IPP Rev:G
 06.12.08
 per ECN 886
 EC

 IPP Rev:H
 07-04-30
 As per Rev D
 JLM

IPP Rev:I 08-06-12 add comment in seq. 21 DD verified by:EC IPP rev J 11.04.21 DEO D412-664-243-E-1 EC verified DD IPP REV:K 11.10.03 DEO D412-664-243-E-2 DD verf:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D412-664-203		Manufactured	No				Each	6.0000		1	/1		
Crosstube Aft													
ı				Location		Loc Qty	<u>Lo</u>	c Code					
				FG103	7	4							
				831	82	1							
				831	83	1							
				831	84	1							
				831	85	1			******				
				Return2012		2							
				670	58	1			<u>·</u>				
				674	34	i							

Instructions for RA 111377 D412-664-203 B83182 CHG008

- Box was returned
- NO KIT
- Tube has large mark from being dragged see pic
- Large mark between center support and chamfering shield see pic
- Have Engineering sign off tube as SCRAP
- Need work order to scrap tube

Time Estimate = 1 HOUR ONLY

Departments Required: Quality Control

Pictures Attached = YES

Instructions for RA 111377 D412-742-018 B75363 CHG002

- Box was not damaged
- Kit complete
- Needs new BATCH #
- Needs new Paper Work & Labels

<u>Time Estimate</u> = 1 HOUR ONLY (stores)

Departments Required: Stores (restocking)

<u>Pictures Attached</u> = NO